

INSTITUTE WORKS DEPARTMENT
ELECTRICAL DIVISION

Dated: 20/10/2020

No. ED/EE/301

QUOTATION NOTICE

M/s
.....
.....
.....

Dear Sirs,

Sealed quotations are invited from the Authorized dealer of Greaves Cotton/ specialized agency by the undersigned on behalf of the Director, IIT Kanpur, "Replacement of defective DGC-7 Genset controller for PROCOM of DG set 1x250KVA installed at Hall-12." As per enclosed Bill of Quantity/ overleaf, so as to reach in this office on or before 27/10/2020 up to 3.00 PM and the quotation will be opened on the same day at 3.30PM in the presence of quotationers or their representative who want to be present.

The terms and conditions of the quotation are as under:

1. The quotations should be submitted in a properly sealed envelop, addressed to the undersigned. The enquiry nos. and date should invariably quoted on the top of the envelop.
2. The time allowed for carrying out the above noted work is **14(Fourteen) Days**.
3. The rates quoted should be exclusive of GST, no other tax is payable except GST. GST shall be quoted separately.
4. Security @ 10% shall be deducted from the bills which shall be released on successful completion of defect liability period of six months.
5. Earnest Money of **Rs.Nil/-** is to be submitted in the form of FDR pledged in favour of the Director, IIT Kanpur alongwith the quotation. The earnest money of the unsuccessful quotationers will be returned within one month's time. (Estimated cost **Rs.21699.00**)
6. The quotations shall remain valid for 90 days from the date of opening.
7. Income tax & Trade tax will be recovered as per Government norms from the bill and the amount so recovered will be deposited in the State Bank of India at the credit of the firm.
8. The earnest money/Security deposit will be regulated as per the norms of C.P.W.D.
9. The Institute reserves the right of accepting or rejecting any quotations without assigning any reason thereof.
10. The firm should be have an experienced of servicing of DG set.
11. The firm should be have an experienced of replacement of engine controller of DG sets.