


QUOTATION

Name of work:- Replacement of defective Engine Controller EMS 936 of DG set 1x250KVA installed at Image Engineering Building.

S.N	Description of item	Qty	Unit	Rate	Amount
1	Repairing / Repalcement of defective Engine controller EMS936 of DG sets 250KVA as instructed by the engineer Incharge as required complete	1.00	each		

TOTAL Rs. _____


राघवेंद्र सिंह
RAGHVENDRA SINGH !
अधिराणी अडिपंता (वि०) E.E. (Elect.)
सं०नि०वि०, मा० प्री० संस्थान, कानपुर
I.W.D., I.I.T., Kanpur
