


QUOTATION

Sub: Replacement of defective ceiling fans & wall fans in ACES-306, Director Office, ACES-413, NL-I-312, Structure Lab, WL-218, SL-116, FB-613, Biomaterial Lab and light fitting in R-1 Lab at Academic Area.

| S.N. | Description | Qty. | Unit | Rate | Amount |
|------|---|-------|------|------|--------|
| 1 | S/F, connecting, testing and commissioning 50 watt LED flood light luminaries with pressure die cast aluminium housing IP65 etc.as reqd.(JETA COMPACTO IP65 CAT No.JETACOMPECTOFL50WLED757LT G) make Havells or equivalent approved make) | 2.00 | Nos. | | |
| 2 | Supply, Installation, testing & commissioning of Ceiling fan of following 220 volts 50 Hz Heavy Duty without regulator I/c wiring the down rods of standard length up to 30 cm with 1.5 sqmm PVC insulated copper conductor single core cable etc as reqd(Leganza make Havells) | | | | |
| a | 1200 mm | 3.00 | Nos. | | |
| 3 | S & F of 400 mm sweep AC 230/250 volts, 50 HZ wall mounting revolving fan with brackets etc. complete | 8.00 | Nos. | | |
| 4 | Dismantling of ceiling fan / rally fan / all type fitting without regulator I/c depositing in store etc as reqd. | 11.00 | Nos. | | |

Total Rs.


RAGHVENDRA SINGH
इसिस्टांती इन्जिनियर (वि०) E.E. (Elect.
अ.वि.वि०, भा०पी० संस्थान, काठगुड
D., I. I. T., Kanpur