

QUOTATION

Sub:- Rewinding & overhauling ceiling fans & exhaust fans in SL Ground floor, Director Banglo, ACES 3rd floor, Samtal-309, SL-116 etc other offices and labs in academic area on complaint basis.


S.N	DESCRIPTION	QTY	UNIT	RATE (In words & Figures)	AMOUNT
1	Overhauling of ceiling fan of any size including dismantling and refixing of fan, bearings, checking, cleaning the all parts and supply & replacement of rubber real, rubber rings, nut bolts, hanger clamps, bearing plates, cotter/ split pin, varnishing if reqd etc, reassembling testing and commissioning of fan as required complete.	30.00	Nos.		
2	Supplying and fixing following capacity capacitor suitable for ceiling fan / exhaust fan / air-curtain etc..				
a	2.5 mfd	12.00	Nos.		
3	Rewinding of ceiling fans of following sizes i/c dismantling of rotor cutting the damaged winding and providing rewinding along with insulation paper, varnish, connecting copper leads of suitable quality including dismantling and refixing from normal/abnorml height and refixing as required.				
a	Old Model 1200 mm / New Model 1400mm	6.00	Nos.		
4	Dismantling & disconnecting and refixing of exhaust fan from 12" to 24 " size with required nut bolts, fasteners, rag bolts etc. as required.	7.00	Nos.		
5	Overhauling of exhaust fan of any size including dismantling of all parts and cleaning the fan with Diesel / petrol removing ball bearing/ bush and refixing after greasing/ oiling including testing and commissioning as required complete.	7.00	Nos.		
6	Repairing of housing for bearing side /bush side /in fan body in ceiling fan /exhaust fan /rally fan etc.	7.00	Nos.		

S.N	DESCRIPTION	QTY	UNIT	RATE	AMOUNT
-----	-------------	-----	------	------	--------

(In words & Figures)

- 7 Rewinding of exhaust fans of following sizes
i/c dismantling cutting the damaged winding
and providing rewinding along with
insulation paper, varnish, connecting copper
leads of suitable quality including
dismantling and refixing from
normal/abnorml height and refixing as
required.(old burnt wire shall be retain by
the contactor.)
- a Rewinding of exhaust fan 18" 3.00 Nos.
- 8 Carriage of Ceiling fan and regulator / 18.00 Nos.
exhaust fan from store to site as reqd.

Total Rs.


अधिकारी अभियन्ता (वि)/ए.ए. (एल.ए.)
वा. प्रो. कल्याण, कानपुर
I.I.T. Kanpur
