


QUOTATION

Name of Work:- Replacement of defective and damaged Gate Valve & nipples in Solar water heating system installed for Blocks of Hall-12 and other associated works

S. No	Description of Items	Qty	Unit	Rate (In words & Figures)	Amount
1	Supplying and fixing testing and commissioning of following Size valve ISI marked size as mentioned below with insulation as per standard specification.				
a)	GM gate Valve 25 mm	8.00	Nos.		
b)	GM gate Valve 32 mm.	6.00	Nos.		
2	Providing and fixing of following size fo SS fittings in pipe line with complete as required				
a)	SS nipple Size of 1" x 6"	7.00	Nos.		
b)	SS nipple Size of 1 1/4" x 6"	28.00	Nos.		
c)	SS Union 32 mm	14.00	Nos.		
3	Providing & fixing 50 mm thick more than 48 Kg/cu Mtr glass wool insulation wrapped with wire mesh etc as required complete on 20/25/32 size hot water pipe line.	50.00	Mtrs.		
4	Providing & fixing 26 swg thick aluminium sheet cladding with screw make Hindalco or its equivalent approved make etc as required complete.	50.00	mtr.		
5	Structural steel work riveted, bolted or welded in built up sections, trusses and framed work, including cutting, hoisting, fixing in position and applying a priming coat of approved steel primer all complete.	300.00	Kg.		
6	Dismantalling & refixing of pipe line by providing & fixing required fittings etc complete	80.00	Mtrs.		
Total Rs.					


राघवेंद्र सिंह
RAGHVENDRA SINGH
अपिग्रामी अडिथंला (वि०) E.E. (Elect.)
सं०वि०वि०, वा०पी० संस्थान, कानपुर
I.W.D., I.I.T., Kanpur